
Canadian Prices 25% Higher

ZEBCO
BRUNSWICK CORPORATION
CONSUMER DIVISION
POST OFFICE BOX 270,
TULSA, OKLAHOMA 74101

# ZEBCO PARTS LIST AND ORDER BLANK
# MODEL 909

**PLEASE ORDER BY PART NUMBER, NOT KEY NUMBER**




100
33
26
160

IF REQUIRED REPAIRS CANNOT BE MADE AT YOUR NEAREST FACTORY APPROVED SERVICE STATION, YOU MAY ORDER THE FOLLOWING REPLACEMENT PARTS DIRECT FROM THE FACTORY OR RETURN REEL TO FACTORY.

Your Order No. _____ Date _____

Charge To _____ Ship To _____

Address _____ Address _____

City & State _____ City & State _____

## DEFECTIVE PARTS REPLACED AT FACTORY ONLY

| KEY NO. | DESCRIPTION | PART NO. | QUANTITY | PRICE | EXTENSION |
|---|---|---|---|---|---|
| 1 | Body Assembly | GZ–1-2-SA | | $7.00 | |
| 2 | Crank Nut | BZ–3 | | .15 | |
| 4 | Clutch Shaft | GZ–7-2-SA | | .50 | |
| 5 | Crank Shaft Assembly | MZ–8-1-SA | | 2.00 | |
| 6 | Thumb Stop | GZ–9-1 | | .50 | |
| 7 | Spinner Head | GZ–10-1-SA | | 3.00 | |
| 8 | Pinion Gear | JZ–11-1 | | .35 | |
| 9 | Center Shaft | GZ–15-2 | | 1.00 | |
| 9A | Center Shaft Assembly | GZ–15-2-SA | | 2.00 | |
| 10 | Crank Handle | LZ–18-AS | | 1.50 | |
| 11 | Center Shaft Spring | GZ–20 | | .15 | |
| 12 | Spool (Empty) | GZ–21-1 | | 1.33 | |
| 13 | Center Shaft Clip | WZ–22 | | .05 | |
| 14 | Back Cover Assembly | GZ–23-1-SA | | 3.00 | |
| 15 | Front Cover | GZ–24-1-SA | | 2.50 | |
| 16 | Shaft Retainer Clip | PZ–30 | | .10 | |
| 17 | Spool Clip | GZ–34 | | .20 | |
| 18 | Anti-Reverse Drag | GZ–52-1 | | .25 | |
| 19 | Line Guide Retainer (Not Shown) | GZ–69 | | .10 | |
| 20 | Nylon Washer | LZ–54 | | N/C | |
| 21 | Clutch Spring | PZ–85 | | .25 | |
| 22 | Control Clip Retainer | GZ–73 | | .05 | |

## EXTRA SPOOLS OF LINE FOR MODEL 909

| | | | | | |
|---|---|---|---|---|---|
| | Spool with 6 lb. test line | GZ–21-1-6 | | $3.15 | |
| | Spool with 8 lb. test line | GZ–21-1-8 | | 3.15 | |
| | Spool with 10 lb. test line | GZ–21-1-10 | | 3.15 | |
| | Spool with 12 lb. test line | GZ–21-1-12 | | 3.15 | |

(Continued on Reverse Side)