



HONDA 35CC LITE

⚠ IMPORTANT NOTICE ⚠

2012-13 HONDA 35cc LITE OWNERS

When unpacking your new Honda Lite auger by StrikeMaster, **DO NOT** remove the green intake gasket located on your engine (see photo below). Removal of green intake gasket will affect proper engine operation.

If removed, replacement of the green intake gasket is **NOT** covered under the Honda or StrikeMaster limited warranty.

Contact your local authorized Honda repair center or visit us on-line at www.strikemaster.com and click the **Find Service Centers** button. Click on the **Visit Honda** button for complete details.

It is recommended that you keep this notice with your Owners Manual.

Green Intake Gasket



Visit our website for up to date service center listings.
www.strikemaster.com

